







3 Faz Motor Kumanda Çift Devir Şalterleri					
Kod No	Faz Sayısı	Kademe	Anma Termik Akımı (A)	Hızlı Montaj	Anahtarlı Kafa Uygulanabilir
2149.02.5.1	3 Faz	0-1-2	10	✓	✓
2149.02.5.2	3 Faz	1-0-2	10	✓	✓
2149.02.5.3	3 Faz	0-1-2	16	✓	✓
2149.02.5.4	3 Faz	1-0-2	16	✓	✓
2149.02.5.5	3 Faz	0-1-2	20	✓	✓
2149.02.5.6	3 Faz	1-0-2	20	✓	✓
2149.02.5.7	3 Faz	0-1-2	25	✓	✓
2149.02.5.8	3 Faz	1-0-2	25	✓	✓



### Kontak Şeması



2149.02.5.1  
2149.02.4.3  
2149.02.4.5  
2149.02.4.7



2149.02.5.2  
2149.02.4.4  
2149.02.4.6  
2149.02.4.8